



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Patrick Bateman (p.bateman@kosinm.com)
Submission Date:	Aug 14, 2019 2:16:07 PM MDT
Server Receive Date:	Aug 14, 2019 2:17:03 PM MDT
Reference Number:	20190814-18114302730
Location:	3601 N 1st St, Bloomfield, NM 87413, USA Aug 14, 2019 2:15:13 PM MDT [View Map]

Information

Name	p.bateman@kosinm.com
Date	Aug 7, 2019
Well Name	COX GAS UNIT 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Well Sign in good shape

Photo of second corrective action completed



Completed work description of corrective action 2

Operator debris removed from pad

Completed work description of corrective action 3

.

Completed work description of corrective action 4

Summary of all work completed

.
Cleaned up operator debris as noted in inspection.
Removed any other trash and debris from pad.
Checked inspection items including erosion control
and well signs.