



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Patrick Bateman (p.bateman@kosinm.com)  
Submission Date: Aug 20, 2019 7:37:21 AM MDT  
Server Receive Date: Aug 20, 2019 4:44:01 PM MDT  
Reference Number: 20190820-18114896435  
Location: 3601 N 1st St, Bloomfield, NM 87413, USA  
Aug 20, 2019 7:37:01 AM MDT [ [View Map](#) ]

## Information

Name p.bateman@kosinm.com  
Date Aug 7, 2019  
Well Name ROBERTSON GAS UNIT 19-01 2  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Compliance Inspection Actions

Photo of first corrective action completed



Completed work description Corrective Action 1

Well sign

Photo of second corrective action completed



Completed work description of corrective action 2

Installed markers for rig anchors

Photo of third corrective action completed



Completed work description of corrective action 3

Completed work description of corrective action 4

Summary of all work completed

Markers

.

Added rig anchor markers to all 4 rig anchors.

Cleaned up trash and debris and checked all other punch list items.