



Form Information

---

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Patrick Bateman (p.bateman@kosinm.com)
Submission Date:	Aug 23, 2019 2:05:39 PM MDT
Server Receive Date:	Aug 23, 2019 2:05:45 PM MDT
Reference Number:	20190823-18115264550
Location:	2351 CO-151, Ignacio, CO 81137, USA Aug 23, 2019 2:05:20 PM MDT [ <a href="#">View Map</a> ]

Information

---

Name	p.bateman@kosinm.com
Date	Aug 8, 2019
Well Name	GEARHART GAS UNIT B 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions
Completed work description Corrective Action 1	.
Completed work description of corrective action 2	.
Completed work description of corrective action 3	.
Completed work description of corrective action 4	.
Summary of all work completed	It was noted that super sacks and pallets were stored on location. At time of inspection all items had been removed belonging to land owner. Cleaned up small wire debris and other small trash and checked all other inspection items.