

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Photo 1 PU and WH sign. WH sign emergence contact number is not a working number



Photo 2 WH Stained soil around WH. Debris: dead weed around well head.

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Photo 3 stained soil around WH



Photo 4 Stained soil around PU motor

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Colorado Oil and Gas Conservation Commission
Sep 12, 2019 12:55:47

Photo 5 stained soil around PU motor



Colorado Oil and Gas Conservation Commission
Sep 12, 2019 12:56:12

Photo 6 Unused equipment: motor and oil jugs. Weeds

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Photo 7 TNK BTRY Sign does not have a working emergency number. WEEDS



Photo 8 Loc pic WEEDS in and around TNK BTRY and vertical separator.

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Photo 9 vertical separator. WEEDS in and around containment



Photo 10 loc pic.