

FRAM OPERATING LLC – 10310

Location ID # 334483

API # 05-077-09350 Whiting #26-5

Inspection Date : 9/9/2019



GoogleEarth view of location area showing access road with entrance off Blue Sage Dr. Image date 6/17/2016.



**GoogleEarth view of location.
Image date 6/17/2016**

FRAM OPERATING LLC – 10310

Location ID # 334483

API # 05-077-09350 Whiting #26-5

Inspection Date : 9/9/2019



Location entrance NE corner looking SW.



Location overview from SE corner looking NW

FRAM OPERATING LLC – 10310

Location ID # 334483

API # 05-077-09350 Whiting #26-5

Inspection Date : 9/9/2019



**API # 05-077-09350 Whiting #26-5 wellhead looking NE.
Shut in.**



**API # 05-077-09350 Whiting #26-5 wellhead
with bradenhead valve exposed.**

FRAM OPERATING LLC – 10310

Location ID # 334483

API # 05-077-09350 Whiting #26-5

Inspection Date : 9/9/2019



Separator with sign



Meter housing



FRAM OPERATING LLC – 10310

Location ID # 334483

API # 05-077-09350 Whiting #26-5

Inspection Date : 9/9/2019



View from N side of meter housing looking S.



Meter housing to gathering line riser.

FRAM OPERATING LLC – 10310

Location ID # 334483

API # 05-077-09350 Whiting #26-5

Inspection Date : 9/9/2019



**Tank battery looking NW.
Weed debris.**



**Tank Battery looking NE.
Weed debris.**

FRAM OPERATING LLC – 10310

Location ID # 334483

API # 05-077-09350 Whiting #26-5

Inspection Date : 9/9/2019



**Large soil stockpile on SE edge of location.
Looking NE. Weed debris.**



Junk cable.

FRAM OPERATING LLC – 10310

Location ID # 334483

API # 05-077-09350 Whiting #26-5

Inspection Date : 9/9/2019



**4" Gathering Line riser located ~ 680' NW of well.
Looking SE**



**4" Gathering Line riser located ~ 680' NW of well.
Looking W.**