

**FRAM OPERATING LLC – 10310****Location ID # 334475**

**API # 05-077-09261 Whiting #25-1**

**Inspection Date : 9/9/2019**



**GoogleEarth view of location area showing access road with entrance off Blue Sage Dr. Image date 6/17/2016.**



**GoogleEarth view of location.**  
**Image date 6/17/2016**

**FRAM OPERATING LLC – 10310**

**Location ID # 334475**

**API # 05-077-09261 Whiting #25-1**

**Inspection Date : 9/9/2019**



**Access road to location looking N.  
Weeds.**



**Location overview from S entrance looking N.  
Weeds.**

**FRAM OPERATING LLC – 10310**

**Location ID # 334475**

**API # 05-077-09261 Whiting #25-1**

**Inspection Date : 9/9/2019**



**Wellbore with fencing and sign. Looking N.  
4\"/>**



**Surface casing with cover plate in corrugated cellar.**

**FRAM OPERATING LLC – 10310**

**Location ID # 334475**

**API # 05-077-09261 Whiting #25-1**

**Inspection Date : 9/9/2019**



**Looking S from N side of 4" Gathering line riser.  
Green hose on ground is for private irrigation.**



**4" Gathering line riser.  
Green hose on ground is for private irrigation.**

**FRAM OPERATING LLC – 10310**

**Location ID # 334475**

**API # 05-077-09261 Whiting #25-1**

**Inspection Date : 9/9/2019**



**Soil stockpile on NW corner of pad.  
Weeds.**



**Soil stockpile on SE edge of pad.  
Weeds.**