

Inspection Photos
Location Name: McCoy, Phillip unit E #1A
Location ID: 332868



Photo #1 WH sign



Photo #2 WH



Inspection Photos
Location Name: McCoy, Phillip unit E #1A
Location ID: 332868



Photo #3 unused Equipment



Photo #4 Weeds growing over possible access road

Inspection Photos
Location Name: McCoy, Phillip unit E #1A
Location ID: 332868



Photo #5 TB sign



Photo #6 LACT



Inspection Photos
Location Name: McCoy, Phillip unit E #1A
Location ID: 332868



Photo #7 TB



Photo #8 Gas meter

Inspection Photos
Location Name: McCoy, Phillip unit E #1A
Location ID: 332868



Photo #9 ECD



Photo #10 Heated Horizontal Searators

Inspection Photos
Location Name: McCoy, Phillip unit E #1A
Location ID: 332868



Photo #11 Heated Horizontal Sclarators