

Inspection Photos
Location Name: 1415 Corp Gas unit G #1
Location ID: 332999



Photo #1 WH sign



Photo #2 PJ

Inspection Photos
Location Name: 1415 Corp Gas unit G #1
Location ID: 332999



Photo #3 Electric transformers, meter box and electric panel

Photo #4 Weeds growing around WH.

Inspection Photos
Location Name: 1415 Corp Gas unit G #1
Location ID: 332999



Photo #5 Stained soil under flow line riser. Possible leak