

Inspection Photos
Location Name: COLOROW 21-24
API#: 05-071-07040
INSP. #: 695101333



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: COLOROW 21-24
API#: 05-071-07040
INSP. #: 695101333



**PHOTO 3: UNUSED EQUIPMENT 2" PIPE IN PIT. REMOVE
UNUDED EQUIPMENT, COMPLY WITH RULE 603.f. CA DATE
10-12-19**



**PHOTO 4: PRODUCED WATER LEVEL IN PIT IS ABOVE
THE 2' FREEBOARD MARKER. SPOKE WITH JACK
WISEMAN BY PHONE TO LOWER PIT LEVEL. Lower
fluid level so at least two feet of freeboard exists
per Rule 902.b.**

Inspection Photos
Location Name: COLOROW 21-24
API#: 05-071-07040
INSP. #: 695101333



PHOTO 5: GUY LINE ANCHOR MARKER IS DOWN. Install proper guy line markers per Rule 1003.a



PHOTO 6: PHOTO 5: GUY LINE ANCHOR MARKER IS DOWN. Install proper guy line markers per Rule 1003.a