

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-08945**  
**Date: 9-6-2019**



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with mixed grasses such as western wheatgrass and smooth brome.



Photo 3. View of the erosional channel within the southern project area, corrective action not addressed.



Photo 4. View of reference area east of the well pad comprised of open pinyon juniper woodland.