

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-08910**  
**Date: 9-6-2019**



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with mixed grasses such as western wheatgrass and intermediate wheatgrass, as well as annual weeds such as prickly lettuce and cheatgrass.



Photo 3. View of flowering musk thistles and rosettes within the western project area.



Photo 4. View of reference area west of the well pad comprised of sagebrush shrubland.