

# *Inspection Photos*

*Loc#335889*

*Operator: Laramie*

*Inspection Number: 692401327*

*Inspection Date: 8/20/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of upper level of Location which has not been reclaimed.

August 20, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335889



Photo#2:  
Overview of upper level of Location which has not been reclaimed.

August 20, 2019





Photo#3:  
Overview of lower level of Location which has had Interim installed.

August 20, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335889