

Inspection Photos

Loc#335902

Operator: Laramie

Inspection Number: 692401336

Inspection Date: 9/6/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to East. Inset is staining indicated by arrow .

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335902



Photo#2:

Topsoil stockpile has not been protected from degradation and contamination.




Photo#3:

Topsoil stockpile has not been protected from degradation and contamination.

September 6, 2019



Photo#4:
Silt fence is in disrepair.



Photo#5:
Silt fence is in disrepair.

September 6, 2019



Photo#6:
Weed establishment on fill slopes.

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335902



Photo#7:
Weed establishment on topsoil.

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335902