

Douglas Creek Unit 37

API: 05-103-09315

Inspection: 679705429



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Douglas Creek Unit 37
API: 05-103-09315
Inspection: 679705429

Gas leak



Photo 2. Well head.



Photo 3. Well head master valve.

Douglas Creek Unit 37
API: 05-103-09315
Inspection: 679705429



Photo 4. Tank battery.