

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photo 1 – Tank Battery Sign




Photo 2 – Stained Soil at Wellhead

Inspection Photos
Location Name: Green 1-1
Location ID: 310566




Photo 3 – Stained Soil inside Treater Shed



Photo 4 – Stained Soil inside Treater Shed

Inspection Photos
Location Name: Logan 2H
Location ID: 430811




Photo 5 – Stained Soil at Engine Base



Photo 6 – Stained Soil at Engine Base

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 7 – Oily Wates at Recycle pump



Photo 8 – Oily Wates at Recycle pump, dispose of and install Wildlife Netting



Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 9 – Chemical Tank/Pump at Wellhead, Please install Wildlife netting. Label is fading, please consider new label.



Photo 10 – Unused Equipment on the north side of the ECD and Flare.