

Inspection Photos
Location Name: Wade 02-29
Location ID: 330957



Colorado Oil and Gas Conservation Commission
40.63919, -103.99694, 4804.7ft, 126°
09/12/2019, 14:56:29

Photo 1 – Unused Methanol Tank



Colorado Oil and Gas Conservation Commission
40.63918, -103.99695, 4809.0ft, 270°
09/12/2019, 14:57:09

Photo 2 – Stained Soil at Wellhead

Inspection Photos
Location Name: Wade 02-29
Location ID: 330957



Photo 1 – Unused Methanol Tank