

Inspection Photos

Loc#335476

Operator: Caerus

Inspection Number: 692401345

Inspection Date: 9/6/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View of Location from topsoil stockpile to East.

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus 697 Loc#335476



Photo#2:
South fill slope 5/22/14



Photo#3:
South fill slope 9/6/19

September 6, 2019



Photo#4:
Topsoil stockpile 5/22/14.



Photo#5:
Topsoil stockpile 5/22/14.

September 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus 697 Loc#335476



Photo#6:
Close up of sparsely vegetated South fill slope.



Photo#7:
Senesced weeds at base of South fill slope.

September 6, 2019