

Inspection Photos
Location Name: Carl R Deepe B #1
Location ID:



Photo #1 weeds overgrown around location



Photo #2 WH sign



Inspection Photos
Location Name: Carl R Deepe B #1
Location ID:




Photo #3 Unused meter box, Exposed wires



Photo #4 Unused exposed wires on ground

Inspection Photos
Location Name: Carl R Deepe B #1
Location ID:



Photo #5 Unused concrete slabs, unused unmarked riser no LOTO.



Photo #6 WH appears SI