

Inspection Photos
Operator: BP America
Location/API #: 067-09601
Date: 9-6-2019



Photo 1. View of southern portion of project area from the southeastern edge facing westward. Revegetation is progressing with western wheatgrass and crested wheatgrass.



Photo 2. View of rock checks in the southern project area. These are not a sufficient stormwater BMP for this area.



Photo 3. View of reference area (in background, past wetland vegetation. Reference area vegetation is comprised of open pinyon juniper woodland and sagebrush shrubland.