

Inspection Photos
Operator: BP America
Location/API #: 067-06566
Date: 9-6-2019



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northeastern edge facing westward. Revegetation is progressing with perennial grasses such as western wheatgrass and smooth brome.



Photo 3. View Canada thistles and musk thistles within the interim reclamation area. Approximate 100 musk thistles and 100 Canada thistles observed.



Photo 4. View of reference area north of project area, comprised of irrigated field vegetation such as western wheatgrass, smooth brome, and foxtail barley.