

HALLIBURTON

iCem® Service

EXTRACTION OIL & GAS-EBUS

United States of America, COLORADO

Date: Sunday, June 23, 2019

Coyote Trails 33S-20-1N Production

Job Date: Sunday, June 23, 2019

Sincerely,
Tyler Hill

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0	Real-Time Job Summary	6
1.1	Job Event Log	6
2.0	Attachments.....	11
2.1	Extraction Coyote Trails 33S-20-1N-Custom Results (1).png.....	11

The Road to Excellence Starts with Safety

Sold To #: 369404	Ship To #: 3951535	Quote #:	Sales Order #: 0905780746
Customer: EXTRACTION OIL & GAS-EBUS		Customer Rep: Mike Torres	
Well Name: COYOTE TRAILS		Well #: 33S-20-1N	API/UWI #: 05-123-49914-00
Field: WATTENBERG	City (SAP): ERIE	County/Parish: WELD	State: COLORADO
Legal Description: SW SE-28-1N-68W-1149FSL-2301FEL			
Contractor: ENSIGN DRLG		Rig/Platform Name/Num: ENSIGN 147	
Job BOM: 7523 7523			
Well Type: HORIZONTAL OIL			
Sales Person: HALAMERICA\HX38199		Srvc Supervisor: Prince Perez	

Job				
Formation Depth (MD)	Top	0'	Bottom	17,953'
Job depth MD	17,946'		Job Depth TVD	7,945'
Water Depth			Wk Ht Above Floor	5'

Well Data										
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing	0	9.625	8.921	36			0	1588	0	1588
Casing	0	5.5	4.892	17			0	17946	0	7945
Open Hole Section			8.5				1588	17953	1588	7945

Tools and Accessories									
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make
Guide Shoe	5.5	1		17,946		Top Plug	5.5	1	
Float Shoe	5.5					Bottom Plug	5.5	1	
Float Collar	5.5	1		17,940		SSR plug set	5.5		
Insert Float	5.5					Plug Container	5.5	1	HES
Stage Tool	5.5					Centralizers	5.5		

Fluid Data									
Stage/Plug #: 1									
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft ³ /sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	Spacer	SBM FDP-C1337-18 CEMENT SPACER SYS	50	bbl	12.5	2.74	16.6	6	2,041

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft ³ /sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	Cap	ELASTICEM (TM) SYSTEM	585	sack	13.2	1.6	7.75	8	4,534

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Lead	ELASTICEM (TM) SYSTEM	615	sack	13.2	1.6	7.74	8	4,760
4	Tail	ELASTICEM (TM) SYSTEM	1,630	sack	13.2	1.57	7.66	8	1,630
5	Displacement	MMCR Displacement	20	bbl	8.33			8	
6	Displacement	Displacement	396.2	bbl	8.33			8	
Cement Left In Pipe									
Amount		0 ft			Reason			Wet Shoe	
Mix Water: pH 7		Mix Water Chloride: <300 ppm			Mix Water Temperature: 62 °F				
Cement Temperature: ## °F		Plug Displaced by: 8.33 lb/gal			Disp. Temperature: 62 °F				
Plug Bumped? Yes		Bump Pressure: 2,398 psi			Floats Held? Yes				
Cement Returns: 36 bbls		Returns Density: ## lb/gal			Returns Temperature: ## °F				
Comment									
Pumped 50 bbls of FDP Spacer.									
Pumped 166.7 bbls of Cap cement.									
Pumped 175.25 bbls of Gasstop cement with 1,538 gallons of Latex.									
Pumped 455.8 bbls of Elasticem.									
Pumped 416.2 bbls of fresh water displacement with MMCR in the first 20 bbls.									
Pumped a 5 bbl wet shoe.									
3 bbls back on the floats.									

1.0 Real-Time Job Summary

1.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	DH Density <i>(ppg)</i>	Comb Pump Rate <i>(bbl/min)</i>	PS Pump Press <i>(psi)</i>	Pump Stg Tot <i>(bbl)</i>	Comments
Event	1	Call Out	Call Out	6/22/2019	09:30:00	USER					CREW CALLED OUT AT 09:30, REQUESTED ON LOCATION 17:30. CREW PICKED UP CEMENT, CHEMICALS, AND PLUG CONTAINER FROM FT. LUPTON, CO. BULK 660, 10867096, 10867521, AND PUMP 11189145.
Event	2	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	6/22/2019	14:50:00	USER					CREW DISCUSSED ROUTES, HAZARDS, AND COMMUNICATION WITH CREW.
Event	3	Crew Leave Shop	Crew Leave Shop	6/22/2019	15:00:00	USER					STARTED JOURNEY MANAGEMENT.
Event	4	Arrive at Location from Service Center	Arrive at Location from Service Center	6/22/2019	15:50:00	USER					END JOURNEY MANAGEMENT. MEET WITH CO. MAN TO DISCUSS JOB; SURFACE CASING- 9/58" 36 LB/FT @ 1,588', 5.5" CASING: 17 LB/FT TOTAL 17,946', 8 1/2" HOLE, TD 17,953', 6' SHOE TRAC, TVD- 7,945'. PUMP FRESH WATER DISPLACEMENT. CASING LANDED @ 18:00 6/22/2019.

Event	5	Safety Meeting - Assessment of Location	Safety Meeting - Assessment of Location	6/22/2019	16:00:00	USER					HAZARD HUNT. DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH LOCATION, RIG UP AND WEATHER.
Event	6	Rig-Up Equipment	Rig-Up Equipment	6/22/2019	16:10:00	USER					RIG UP BULK AND MIXING EQUIPMENT.
Event	7	Pre-Job Safety Meeting	Pre-Job Safety Meeting	6/22/2019	20:00:00	USER					MEETING WITH HALLIBURTON AND RIG PERSONNEL. COMMUNICATED POTENTIAL SAFETY HAZARDS AND JOB DETAILS.
Event	8	Rig-Up Completed	Rig-Up Completed	6/22/2019	20:20:00	USER					
Event	9	Start Job	Start Job	6/22/2019	20:23:27	COM4					BEGIN RECORDING JOB DATA.
Event	10	Drop Bottom Plug	Drop Bottom Plug	6/22/2019	20:24:39	COM4					PLUG LEFT CONTAINER, VERIFIED BY CO. MAN.
Event	11	Test Lines	Test Lines	6/22/2019	20:26:43	COM4					PRESSURE TESTED IRON TO 4,700 PSI. KICKOUTS SET @ 500 PSI, KICKED OUT @ 490 PSI, 5TH GEAR STALL OUT @ 2,030 PSI. 4,700 PRESSURE TEST KICKED OUT @ 4,500 PSI
Event	12	Check Weight	Check Weight	6/22/2019	20:28:43	COM4					
Event	13	Pump Spacer 1	Pump Spacer 1	6/22/2019	20:33:24	COM4	12.5	6.5	840	50	PUMP 50 BBLS OF FDP SPACER @ 12.5 LB/GAL, 2.74 CUFT/SK, 16.6 GALL/SK. 50 BBLS CALCULATED TO RETURN TO SURFACE. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 6.5 BBLS/MIN @ 840 PSI.

Event	14	Pump Cap Cement	Pump Cap Cement	6/22/2019	20:42:54	COM4	13.2	8	1200	166.7	PUMPED 585 SKS OF ELASTICEM @ 13.2 LB/GAL, 1.6 FT3/SK, 7.75 GAL/SK. 166.7 BBLS. HOC CALCULATED @ 2,479.6'. CALCULATED 54.3 BBLS TO RETURN TO SURFACE. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 8 BBLS/MIN @ 1,200 PSI
Event	15	Check Weight	Check Weight	6/22/2019	20:45:44	COM4	13.22				
Event	16	Check Weight	Check Weight	6/22/2019	20:57:07	COM4	13.19				
Event	17	Pump Lead Cement	Pump Lead Cement	6/22/2019	21:07:34	COM4	13.42	8.20	546.00	175.25	PUMPED 615 SKS OF GASSTOP ELASTICEM @ 13.2 LB/GAL, 1.6 FT3/SK, 7.74 GAL/SK. 175.25 BBLS. 1,538 GALLONS OF FDP LATEX. HOC CALCULATED @ 4,295.3', TOL CALCULATED @ 2,479.6'. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 8 BBLS/MIN @ 570 PSI
Event	18	Pump Tail Cement	Pump Tail Cement	6/22/2019	21:34:55	COM4	13.32	8.00	1023.00	455.78	PUMP 1,630 SKS OF ELASTICEM @ 13.2 LB/GAL, 1.57 FT3/SK, 7.66 GAL/SK, 455.78 BBLS. HOT CALCULATED @ 11,171.1', TOT CALCULATED @ 6,774.9'. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 8 BBLS/MIN @ 750 PSI.
Event	19	Check Weight	Check Weight	6/22/2019	21:35:18	COM4	13.32				
Event	20	Check Weight	Check Weight	6/22/2019	21:53:11	COM4	13.26				

Event	21	Check Weight	Check Weight	6/22/2019	21:57:42	COM4	13.27					
Event	22	Check Weight	Check Weight	6/22/2019	22:09:37	COM4	13.21					
Event	23	Shutdown	Shutdown	6/22/2019	22:33:19	COM4						SHUTDOWN TO WASH LINES.
Event	24	Drop Top Plug	Drop Top Plug	6/22/2019	22:45:26	COM4						PLUG LEFT CONTAINER, VERIFIED BY CO. MAN.
Event	25	Pump Displacement	Pump Displacement	6/22/2019	22:45:29	COM4	8.33	8.5	2700	416.2		BEGIN CALCULATED DISPLACEMENT OF 416.2 BBLS WITH FRESH WATER. MMCR IN THE FIRST 20 BBLS. PUMP RATE 8.5 BPM @ 2,700 PSI. CAUGHT CEMENT @ 60 BBLS INTO DISPLACEMENT. SPACER TO SURFACE @ 350 BBLS INTO DISPLACEMENT. 50 BBLS OF TUNED SPACER TO SURFACE. CEMENT TO SURFACE @380 BBLS INTO DISPLACEMENT. 36 BBLS OF CEMENT TO SURFACE. SLOW RATE TO 3 BPM @ 390 BBLS INTO DISPLACEMENT.
Event	26	Bump Plug	Bump Plug	6/22/2019	23:45:50	COM4			2898.00			PLUG BUMPED AT CALCULATED DISPLACEMENT. 2,398 PSI PRESSURED 500 PSI OVER BUMP.
Event	27	Shift Tool - Lower	Shift Tool - Lower	6/22/2019	23:48:16	USER			3318.00			SHEARED @ 3,318 PSI FOLLOWED BY A 5 BBL WET SHOE.
Event	28	Check Floats	Check Floats	6/22/2019	23:50:43	USER						RELEASED PRESSURE, FLOATS HELD, 3 BBLS BACK.

Event	29	End Job	End Job	6/22/2019	23:51:54	COM4	STOP RECORDING JOB DATA.
Event	30	Post-Job Safety Meeting (Pre Rig-Down)	Post-Job Safety Meeting (Pre Rig-Down)	6/23/2019	00:00:00	USER	DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH WEATHER, LOCATION AND RIGGING DOWN IRON AND HOSES.
Event	31	Rig-Down Equipment	Rig-Down Equipment	6/23/2019	00:10:00	USER	RIG DOWN BULK AND MIXING EQUIPMENT.
Event	32	Rig-Down Completed	Rig-Down Completed	6/23/2019	02:50:00	USER	
Event	33	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	6/23/2019	03:00:00	USER	CREW DISCUSSED ROUTES HAZARDS AND COMMUNICATION WITH CREW.
Event	34	Crew Leave Location	Crew Leave Location	6/23/2019	03:10:00	USER	THANK YOU FOR USING HALLIBURTON – PRINCE PEREZ AND CREW.

2.0 Attachments

2.1 Extraction Coyote Trails 33S-20-1N-Custom Results (1).png



