

HALLIBURTON

iCem[®] Service

EXTRACTION OIL & GAS-EBUS

Coyote Trails 33W-15-11N

Sincerely,

Alexandria Dionigi

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0	Cementing Job Summary	4
1.1	Executive Summary	4
2.0	Real-Time Job Summary	8
2.1	Job Event Log	8
3.0	Attachments.....	11
3.1	EXTRACTION COYOTE TRAILS PRODUCTION 33W-15-11N-Custom Results.png	11

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Coyote Trails 33W-15-11N** cement **Production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 57 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 369404	Ship To #: 3951532	Quote #:	Sales Order #: 0905791867
Customer: EXTRACTION OIL & GAS-EBUS		Customer Rep: Hans Cary	
Well Name: COYOTE TRAILS		Well #: 33W-15-11N	API/UWI #: 05-123-49912-00
Field: WATTENBERG	City (SAP): ERIE	County/Parish: WELD	State: COLORADO
Legal Description: SW SE-28-1N-68W-1149FSL-2319FEL			
Contractor: ENSIGN DRLG		Rig/Platform Name/Num: ENSIGN 147	
Job BOM: 7523 7523			
Well Type: HORIZONTAL OIL			
Sales Person: HALAMERICA\HX38199		Srvc Supervisor: Thomas Haas	

Job

Formation Name			
Formation Depth (MD)	Top		Bottom
Form Type			BHST
Job depth MD	16750ft		Job Depth TVD
Water Depth			Wk Ht Above Floor
Perforation Depth (MD)	From		To

Well Data

Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing	0	9.625	8.921	36			0	1661	0	1661
Casing	0	5.5	4.892	17			0	16750	0	7440
Open Hole Section			8.5				1661	16751	1661	7440

Tools and Accessories

Type	Size in	Qty	Make	Depth ft	Type	Size in	Qty	Make
					Top Plug	5.5	1	HES
Float Shoe	5.5	1	NCS	16747	Bottom Plug	5.5	1	HES
Float Collar	5.5	1	NCS	16747				
					Plug Container	5.5	1	HES

Fluid Data

Stage/Plug #: 1									
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	FDP-C1337-18	SBM FDP-C1337-18 CEMENT SPACER SYS	50	bbl	12.5	2.74	16.6	8	1693
1 lbm/bbl		FE-2 (100001615)							

5 lbm/bbl		SEM-94P, 35 LB SACK - (1023987)								
205.22 lbm/bbl		BARITE, BULK (100003681)								
5 lbm/bbl		SEM-93P, 35 LB SACK - (1023977)								
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
2	ElastiCem	ELASTICEM (TM) SYSTEM	585	sack	13.2	1.6	7.75	8	4533	
0.75 %		SCR-100 (100003749)								
7.75 Gal		FRESH WATER								
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
3	GasStop	ELASTICEM (TM) SYSTEM	615	sack	13.2	1.6	7.74	8	4760	
0.75 %		SCR-100 (100003749)								
5.24 Gal		FRESH WATER								
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
4	13.2# ElastiCem	ELASTICEM (TM) SYSTEM	1470	sack	13.2	1.57	7.66	8	11260	
7.66 Gal		FRESH WATER								
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
5	MMCR Displacement	MMCR Displacement	20	bbl	8.33			8		
0.50 gal/bbl		MICRO MATRIX CEMENT RETARDER, 5 GAL PAIL (100003781)								
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
6	Displacement	Displacement	369	bbl	8.33			8		
Cement Left In Pipe		Amount	N/A		Reason			Shoe Joint		

Mix Water:	pH 7	Mix Water Chloride:	<300 ppm	Mix Water Temperature:	70 °F
Cement Temperature:	N/A	Plug Displaced by:	FW 8.33 lb/gal	Disp. Temperature:	70 °F
Plug Bumped?	Yes	Bump Pressure:	2330 psi	Floats Held?	Yes
Cement Returns:	57 bbl	Returns Density:	N/A	Returns Temperature:	N/A
Comment PLUG BUMP AT CALCULATED DISPLACEMENT, FINAL CIRCULATING PRESSURE 2330 PSI, DISK SHOE RUPTURE AT 2180 PSI, FLOATS HELD, 2 ½ BBLs BACK. 57 BBLs OF CEMENT TO SURFACE.					

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	DH Density <i>(ppg)</i>	Comb Pump Rate <i>(bbl/min)</i>	DS Pump Press <i>(psi)</i>	Pump Stg Tot <i>(bbl)</i>	Comments
Event	1	Call Out	Call Out	6/26/2019	15:00:00	USER					CREW CALLED OUT AT 15:00 06/26/2019, REQUESTED ON LOCATION 22:00 06/26/2019. CREW PICKED UP CEMENT, CHEMICALS (30 GAL D-AIR, 10 GAL MMCR), 100 LBS SUGAR, AND PLUG CONTAINER FROM FORT LUPTON, CO. BULK 660: 11633846/10989685 Bulk 660: 11527037/11062210 PUMP ELITE: 11645460/11897034 SOFT: 12051660/12240040
Event	2	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	6/26/2019	19:00:00	USER					DISCUSSED ROUTES, HAZARDS, AND COMMUNICATION WITH CREW
Event	3	Crew Leave Yard	Crew Leave Yard	6/26/2019	19:30:00	USER					STARTED JOURNEY MANAGEMENT.
Event	4	Arrive At Loc	Arrive At Loc	6/26/2019	20:30:00	USER					END JOURNEY MANAGEMENT. MEET WITH CO. MAN TO DISCUSS JOB; SURFACE CASING: 9.625" 36# @ 1661', CASING: 5.5" 17# @ 16750', 3' SHOE JOINT, 8.5" OPEN HOLE, TVD @ 7440', 9.9 PPG WELL FLUID, FRESH WATER DISPLACEMENT.
Event	5	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	6/26/2019	21:30:00	USER					HAZARD HUNT. DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH LOCATION, RIG UP AND WEATHER.
Event	6	Rig-Up Equipment	Rig-Up Equipment	6/26/2019	21:45:00	USER					CREW STAGED EQUIPMENT AND RIGGED UP BULK, IRON, AND WATER HOSES TO PERFORM JOB.
Event	7	Pre-Job Safety Meeting	Pre-Job Safety Meeting	6/27/2019	02:45:00	USER	8.82	0.00	-3.00	8.10	MEETING WITH HALLIBURTON AND RIG PERSONNEL. COMMUNICATED

											POTENTIAL SAFETY HAZARDS AND JOB DETAILS.
Event	8	Start Job	Start Job	6/27/2019	03:14:26	COM4	8.45	0.00	-2.00	0.00	START JOB DATA RECORDING.
Event	9	Test Lines	Test Lines	6/27/2019	03:16:00	COM4	8.41	0.00	179.00	2.00	PRESSURE TESTED LINES TO 4800 PSI, 500 PSI KICK OUT AT 540 PSI, 5TH GEAR STALL AT 1800 PSI.
Event	10	Drop Bottom Plug	Drop Bottom Plug	6/27/2019	03:22:18	COM4	8.40	0.00	116.00	2.00	PLUG LEFT PUP JOINT, VERIFIED BY COMPANY MAN.
Event	11	Pump Spacer 1	Pump Spacer 1	6/27/2019	03:22:25	COM4	8.40	0.00	120.00	2.00	PUMP 50 BBLS OF FDP SPACER @ 12.5 LB/GAL, ADDED 10 GAL D-AIR, DENSITY VERIFIED BY PRESSURIZED MUD SCALES.
Event	12	Pump Cap Cement	Pump Cap Cement	6/27/2019	03:31:44	COM4	12.99	3.60	94.00	52.20	PUMP 585 SKS OF ELASTICEM @ 13.2 LB/GAL, 1.6 YIELD, 7.75 GAL/SK, 166.7 BBLS, CALCULATED TOC @ SURFACE, DENSITY VERIFIED BY PRESSURIZED MUD SCALES.
Event	13	Pump Lead Cement	Pump Lead Cement	6/27/2019	03:53:18	COM4	13.16	8.50	526.00	179.40	PUMP 615 SKS OF GASSTOP @ 13.2 LB/GAL, 1.57 YIELD, 7.7 GAL/SK, 175 BBLS, CALCULATED TOL 2388', MIX WATER MIXED WITH 1538 GAL OF LATEX AND 15 GAL D-AIR, DENSITY VERIFIED BY PRESSURIZED MUD SCALES.
Event	14	Pump Tail Cement	Pump Tail Cement	6/27/2019	04:14:45	COM4	13.17	8.50	633.00	181.60	PUMP 1470 SKS OF ELASTICEM @ 13.2 LB/GAL, 1.57 YIELD, 7.66 GAL/SK, 411 BBLS, CALCULATED TOT @ 6677', DENSITY VERIFIED BY PRESSURIZED MUD SCALES.
Event	15	Cement At Bottom	Cement At Bottom	6/27/2019	04:15:54	USER	13.15	8.40	1255.00	9.80	BOTTOM PLUG RUPTURED @ 1450 PSI.
Event	16	Shutdown	Shutdown	6/27/2019	05:07:41	COM4	13.30	0.00	116.00	435.00	SHUTDOWN TO WASH PUMPS/LINES AND DROP TOP PLUG.
Event	17	Drop Top Plug	Drop Top Plug	6/27/2019	05:19:15	COM4	-0.15	0.00	5.00	453.80	PLUG LEFT PLUG CONTAINER, VERIFIED BY COMPANY MAN.

Event	18	Pump Displacement	Pump Displacement	6/27/2019	05:19:18	COM4	-0.17	0.00	6.00	453.80	BEGIN PUMPING CALCULATED DISPLACEMENT OF 389 BBL FRESH WATER, 10 GAL OF MMCR ADDED TO THE FIRST 20 BBL.
Event	19	Cement Returns to Surface	Cement Returns to Surface	6/27/2019	06:06:10	USER	8.24	5.20	2483.00	366.20	CEMENT RETURN TO SURFACE 332 BBLS IN DISPLACEMENT. 57 BBLS OF CEMENT TO SURFACE
Event	20	Bump Plug	Bump Plug	6/27/2019	06:12:28	COM4	8.24	0.00	2499.00	393.70	PLUG BUMPED AT CALCULATED DISPLACEMENT, FINAL CIRCULATING PRESSURE OF 2330 PSI.
Event	21	Bump Plug	RUPTURE DISK	6/27/2019	06:13:32	USER	8.26	1.90	3169.00	394.40	PRESSURE UP TO RUPTURE SHOE DISK, RUPTURE @ 3180 PSI.
Event	22	Other	Wet Shoe	6/27/2019	06:13:47	USER	8.24	4.60	2383.00	395.20	PUMP 3 BBLS WET SHOE.
Event	23	Other	CHECK FLOATS	6/27/2019	06:14:42	USER	8.24	4.50	2398.00	399.30	RELEASED PRESSURE BACK TO THE TRUCK, FLOATS HELD, RECIEVED 2 1/2 BBL BACK.
Event	24	End Job	End Job	6/27/2019	06:16:21	COM4	8.19	0.00	8.00	0.00	END JOB DATA RECORDING.
Event	25	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	6/27/2019	06:20:00	USER	8.18	0.00	0.00	0.00	DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH WEATHER, LOCATION AND RIGGING DOWN IRON AND HOSES.
Event	26	Rig-Down Completed	Rig-Down Completed	6/27/2019	07:30:00	USER					ALL HALLIBURTON ITEMS WERE STOWED FOR TRAVEL.
Event	27	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	6/27/2019	07:45:00	USER					DISCUSSED ROUTES HAZARDS AND COMMUNICATION WITH CREW.
Event	28	Crew Leave Location	Crew Leave Location	6/27/2019	08:00:00	USER					THANK YOU FOR USING HALLIBURTON - THOMAS HAAS AND CREW.

3.0 Attachments

3.1 EXTRACTION COYOTE TRAILS PRODUCTION 33W-15-11N-Custom Results.png

