

Inspection Photos

API: 05-071-06399

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/16/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019

Inspection Photos



Photo 1. Facing southeast at the beginning of the reclaimed access road. Red arrow points to noxious weeds located in this area. (Canada thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019

Inspection Photos



Photo 2. Facing southeast along the reclaimed access road. There is annual weeds along this area and some perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019

Inspection Photos



Photo 3. There are noxious weeds (Canada thistle) at the first rock rip/rap drainage along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019

Inspection Photos



Photo 4. Perennial vegetation is establishing well further along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019

Inspection Photos



Photo 5. Facing southeast along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019

Inspection Photos



Photo 6. There are noxious weeds near the location that appear to have been treated. Some of which still have seed heads which should be removed and bagged.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019

Inspection Photos



Photo 7. There were a pile of noxious weeds near the location shown in the previous photo. These weed should have been bagged and removed to prevent a future problem since they contained seed heads.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019

Inspection Photos



Photo 8. Facing south toward the location. Perennial vegetation is establishing well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06399 | Date: 9/16/2019