

Inspection Photos
Location Name: Calvary USX EE 29-19
Location ID: 306408



Photo 1: Location



Photo 2: Wellhead Sign

Inspection Photos
Location Name: Calvary USX EE 29-19
Location ID: 306408



Photo 3: Wellhead



Photo 4: Unused Equipment



Inspection Photos
Location Name: Calvary USX EE 29-19
Location ID: 306408



Photo 5: Tank Battery Signs



Photo 6: Centralized Tank Battery



Inspection Photos
Location Name: Calvary USX EE 29-19
Location ID: 306408



Photo 7: Unused Equipment




Photo 8: Unused Equipment



Inspection Photos
Location Name: Calvary USX EE 29-19
Location ID: 306408



Photo 9: Weeds



Photo 10: Weeds

