

Inspection Photos
Location Name: Lamb Dalton Nessu #13
Location ID: 317947





Photo 1 loc pic WH and PU.



Photo 2 Weeds and stained soil around well head

Inspection Photos
Location Name: Lamb Dalton Nesssu #13
Location ID: 317947



Colorado Oil and Gas Conservation Commission
Sep 17, 2019 08:28:19



Colorado Oil and Gas Conservation Commission
Sep 17, 2019 08:28:46

Photo 3 WH sign does not reflect current operator and wrong emergency contact number. Stained soil under PU

Photo 4 Dead weeds in and around PU

Inspection Photos
Location Name: Lamb Dalton Nessu #13
Location ID: 317947



Photo 5 Dead weeds around Pu and WH



Photo 6 Electric panel for PU is in the off position. Unused equipment: electrical wiring sticking out of ground.