

Inspection Photos
Location Name: NESSSU #14
Location ID:318302



Photo 1 PU and WH. WEEDS

Photo 2 WH sign does not reflect current operator.
Emergency contact number is incorrect.

Inspection Photos
Location Name: NESSSU #14
Location ID:318302



Colorado Oil and Gas Conservation Commission
Sep 17, 2019 08:58:19

Photo 3 electric breaker box for PU is in the Off position.



Colorado Oil and Gas Conservation Commission
Sep 17, 2019 08:58:44

Photo 4 WEEDS in and around PU and WH.