

**Inspection Photos**  
**Location Name: North Platte /14-36**  
**Location #: 428456**



Colorado Oil & Gas Conservation Commission  
40.35195, -104.39024, 1370.0m, 58°  
09/17/2019 12:26:53 PM

**Photo #1**

**North Platte 14-36 (05-123-35367) Wellsite**

**Shut-In | SI**



Colorado Oil & Gas Conservation Commission  
40.35202, -104.39023, 1367.0m, 59°  
09/17/2019 12:26:39 PM

**Photo #2**

**North Platte X-D-35HZ (05-123-35443) Wellsite**

**Producing | PR**

**Inspection Photos**  
**Location Name: North Platte /14-36**  
**Location #: 428456**



**Photo #3**  
**Latham F-J-1HZ (05-123-35441) Wellsite**  
**Shut-In | SI**



**Photo #4**  
**North Platte 14-36, X-D-35HZ Battery**  
**Latham F-J-35HZ**  
**Active**

**Inspection Photos**  
**Location Name: North Platte /14-36**  
**Location #: 428456**



**Photo #5**  
**North Platte 14-36, X-D-35HZ Compressors**  
**Latham F-J-35HZ**  
**Active**



**Photo #6**  
**North Platte 14-36, X-D-35HZ Battery**  
**Latham F-J-35HZ**  
**Stained soil**  
**Crude oil tanks 2, 3**

**Inspection Photos**  
**Location Name: North Platte /14-36**  
**Location #: 428456**



**Photo #7**  
**North Platte 14-36, X-D-35HZ Battery**  
**Latham F-J-35HZ**  
**Stained soil**  
**Crude oil tanks 3, 4**