

Inspection Photos

API: 05-071-08873

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-08873 | Date: 9/16/2019

Inspection Photos



Photo 1. Well sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08873 | Date: 9/16/2019

Inspection Photos



Photo 2. There is a piece of metal from the old shed that remains at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08873 | Date: 9/16/2019

Inspection Photos



Photo 3. Facing toward eastern side of the location. Vegetation is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08873 | Date: 9/16/2019

Inspection Photos



Photo 4. Facing west toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08873 | Date: 9/16/2019

Inspection Photos



Photo 5. The fence is not maintained around the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08873 | Date: 9/16/2019