

Inspection Photos

API: 05-071-09373

05-071-09374

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019

Inspection Photos



Photo 1. Facing northwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019

Inspection Photos



Photo 2. There is erosion issues along the access road as it ascends the hill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019

Inspection Photos



Photo 3. Vegetation is not established along the side of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019

Inspection Photos



Photo 4. There are no BMP's to prevent erosion on the side of the road. It looks like check dams have been displaced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019

Inspection Photos



Photo 5. Facing northwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019

Inspection Photos



Photo 6. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019

Inspection Photos



Photo 7. Facing west toward the fill slope which is mostly rock.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019

Inspection Photos



Photo 8. Facing east at the location. Vegetation is well established on the pad surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09373 | Date: 9/16/2019