

Inspection Photos
Operator: BP America
Location/API #: 067-07741
Date: 9-10-2019



Photo 1. View of the project area from the southeastern edge facing center.



Photo 2. View of the southern fill slope from the southeastern edge facing westward. Revegetation is progressing with western wheatgrass and intermediate wheatgrass.



Photo 3. View of erosional channel approximately 1 foot wide and deep within the southwestern project area (facing upslope).



Photo 4. View of erosional channel approximately 2 feet wide and deep within the southwestern project area (facing downslope).



Photo 5. View of reference area northwest of project area, comprised of mixed sagebrush, squaw apple, and juniper woodland.