

Inspection Photos
Location Name: Ewing 23-30, Shannon 24-30 TB
Location ID: 446607



Photo #1 TB sign



Photo #2 TB

Inspection Photos
Location Name: Ewing 23-30, Shannon 24-30 TB
Location ID: 446607



Photo #3 Unused Equipment/ trash



Photo #4 unused, unmarked no LOTO flow line riser.

Inspection Photos
Location Name: Ewing 23-30, Shannon 24-30 TB
Location ID: 446607



Photo #5 HHS, Unused, unmarked no LOTO flow line riser




Photo #6 unused, unmarked no LOTO flow line risers. Red arrow LO but not tagged Yellow no LOTO