

Inspection Photos
Location Name: Harry Ewing C #1
Location ID: 311352



Photo #1 WH sign



Photo #2 PU



Inspection Photos
Location Name: Harry Ewing C #1
Location ID: 311352



Photo #3 electric transformers, electric panel and meter box.



Photo #4 Debris on location

Inspection Photos
Location Name: Harry Ewing C #1
Location ID: 311352



Photo #5 unused fence posts



Photo #6 unused fence post and barbwire

Inspection Photos
Location Name: Harry Ewing C #1
Location ID: 311352



Photo #7 unused pipe