

Inspection Photos
Location Name: UPRR 42 Pan Am G #2
Location ID: 317758



Photo #1 WH sign



Photo #2 electric transformers, electric panel and meterbox.

Inspection Photos
Location Name: UPRR 42 Pan Am G #2
Location ID: 317758



Photo #3 Stained soil around WH

Photo #4 Stained soil around WH.

Inspection Photos
Location Name: UPRR 42 Pan Am G #2
Location ID: 317758



Photo #5 possible leak around tubing.