

Inspection Photos
Location Name: Sam Funakoshi A #1
Location ID: 318417



Photo #1 WH sign faded not legible



Photo #2 PU



Inspection Photos
Location Name: Sam Funakoshi A #1
Location ID: 318417



Photo #3 Electric panel



Photo #4 Weeds growing around WH