

Inspection Photos
Location Name: Sam Funakoshi A #1 & #2 Tank Battery
Location ID: 318417



Photo #1 TB sign

Photo #2 TB

Inspection Photos

Location Name: Sam Funakoshi A #1 & #2 Tank Battery

Location ID: 318417



Photo #3 Weeds growing on TB berm



Photo #4 Weeds growing by heated horiz. Sep.

Inspection Photos

Location Name: Sam Funakoshi A #1 & #2 Tank Battery

Location ID: 318417



Photo #5 Gas meter run



Photo #6 Stained soil by production lines.