

Location:	CPC 67 L#1
Line:	Well to Separator
Technicians:	Cody Baylis
Date	9/4/2019
Time	Pressure (PSI)
2:33:10 PM	0
2:33:40 PM	0
2:34:10 PM	0
2:34:40 PM	0
2:35:10 PM	3.2
2:35:40 PM	7.2
2:36:10 PM	7
2:36:40 PM	25.3
2:37:10 PM	80
2:37:40 PM	94.7
2:38:10 PM	94.6
2:38:40 PM	94.6
2:39:10 PM	94.6
2:39:40 PM	94.6
2:40:10 PM	94.6
2:40:40 PM	94.5
2:41:10 PM	94.5
2:41:40 PM	94.5
2:42:10 PM	94.5
2:42:40 PM	94.5
2:43:10 PM	94.5
2:43:40 PM	94.5
2:44:10 PM	94.5
2:44:40 PM	94.5
2:45:10 PM	94.5
2:45:40 PM	94.5
2:46:10 PM	94.5
2:46:40 PM	94.4
2:47:10 PM	94.4
2:47:40 PM	94.5
2:48:10 PM	94.4
2:48:40 PM	94.4
2:49:10 PM	94.5
2:49:40 PM	94.4
2:50:10 PM	94.4
2:50:40 PM	94.4
2:51:10 PM	94.4
2:51:40 PM	94.4
2:52:10 PM	94.4
2:52:40 PM	94.4
2:53:10 PM	94.4
2:53:40 PM	94.4

2:54:10 PM	94.4
2:54:40 PM	94.4
2:55:10 PM	94.4
2:55:40 PM	94.4
2:56:10 PM	94.4
2:56:40 PM	94.4
2:57:10 PM	94.4
2:57:40 PM	94.4
2:58:10 PM	94.4
2:58:40 PM	94.4
2:59:10 PM	94.4
2:59:40 PM	94.4
3:00:10 PM	94.4
3:00:40 PM	94.4
3:01:10 PM	94.4
3:01:40 PM	94.4
3:02:10 PM	94.4
3:02:40 PM	94.5
3:03:10 PM	94.4
3:03:40 PM	94.4
3:04:10 PM	94.4
3:04:40 PM	94.5
3:05:10 PM	94.4
3:05:40 PM	94.5
3:06:10 PM	94.5
3:06:40 PM	94.5
3:07:10 PM	94.5
3:07:40 PM	94.5
3:08:10 PM	94.5
3:08:40 PM	94.5
3:09:10 PM	94.5
3:09:40 PM	94.5
3:10:10 PM	94.5
3:10:40 PM	94.5
3:11:10 PM	94.5
3:11:40 PM	94.3
3:12:10 PM	82.7
3:12:40 PM	4.6
3:13:10 PM	0
3:13:40 PM	0
3:14:10 PM	0
3:14:40 PM	0
3:15:10 PM	0

Pass/Fail

% loss over 30 minutes	0.42%	Less than 10%	Yes		
% loss in last 5 minutes	0.21%	Less than 1%	Yes		Pass

