

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402168236

Date Received:

09/06/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Jessica Dooling

Phone

970-675-4122

Email

jessica_dooling@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679705225

Inspection Date: 08/26/2019

FIR Submit Date: 08/26/2019

FIR Status: _____

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 316450

Location Name: YELLOW CREEK FEDERAL-61N98W Number: 29SWNE County: RIO BLANCO

Qtrqtr: SWNE Sec: 29 Twp: 1N Range: 98W Meridian: 6

Latitude: 40.028030 Longitude: -108.413310

FACILITY - API Number: 05-103-00 Facility ID: 276268

Facility Name: YELLOW CREEK FEDERAL Number: 29-32-1

Qtrqtr: SWNE Sec: 29 Twp: 1N Range: 98W Meridian: 6

Latitude: 40.028030 Longitude: -108.413310

CORRECTIVE ACTIONS:

1 ☒ CA# 129691

Corrective Action: Install sign to comply with Rule 210.b.

Date: 10/23/2019

Response: CA COMPLETED

Date of Completion: 09/05/2019

Operator Comment: Sign installed to comply with Rule 210.b, see attached photo

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 129692

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/23/2019

Response: CA COMPLETED

Date of Completion: 09/05/2019

Operator
Comment: Valve installed in riser per Rule 605.d, see attached photo

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 129693

Corrective Action: Install sign to comply with Rule 210.b.

Date: 10/23/2019

Response: CA COMPLETED

Date of Completion: 09/05/2019

Operator
Comment: Sign in stalled to comply with Rule 210.b, see attached photo

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective Actions completed 9/5/2019. see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed: _____

Title: Regulator Coordinator

Date: 9/6/2019 10:11:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|-----------------------------|
| 402168236 | FIR RESOLUTION SUBMITTED |
| 402168267 | YCF 29-32-1 Lease Road Sign |
| 402168271 | Valve Installed on Riser |
| 402168275 | YCF 29-32-1 Seperator Sign |

Total Attach: 4 Files