

# Final Reclamation Inspection

September 2, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 318027

Inspection Document #: 697500585

Weld County, CO

NWNE Section 34 T7N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CANAL #2  
Location ID: 318027



**Photo 1.** Photo taken from the entrance of the well location access road, facing West. Photo illustrates a locked gate.

Inspection Photos  
Location Name: CANAL #2  
Location ID: 318027



**Photo 2.** Photo taken from the entrance of the well location access road, facing West. See comments under Photo 1.