

Inspection Photos
Location Name: Koshio Battery
Location ID: 332953



Photo #1 TB sign



Photo #2 TB

Inspection Photos
Location Name: Koshio Battery
Location ID: 332953



Photo #3 Heated vert.sep.



Photo #4 unused, unmarked flow line riser no LOTO.

Inspection Photos
Location Name: Koshio Battery
Location ID: 332953



Photo #5 unused, unmarked flow line riser no LOTO.

Photo #6 unused, unmarked flow line riser no LOTO.

Inspection Photos
Location Name: Koshio Battery
Location ID: 332953



Photo #7 unused, unmarked flow line riser no LOTO.