

# Final Reclamation Inspection

September 2, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-11822

Inspection Document #: 697500587

Weld County, CO

SESE Section 11 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MILLER #1  
API: 05-123-11822



**Photo 1.** Photo taken from the northern well and tank battery location, facing South. Operator has performed final reclamation activities per the previous corrective action inspection. However, crop is not reflective or reference areas; therefore, this will remain in-process.

Inspection Photos  
Location Name: MILLER #1  
API: 05-123-11822



**Photo 2.** Photo taken from the northern well and tank battery location, facing Southwest. See comments under Photo 1.

Inspection Photos  
Location Name: MILLER #1  
API: 05-123-11822



**Photo 3.** Photo taken from the northern well and tank battery location, facing West. See comments under Photo 1.