

Inspection Photos
Location Name: Two E Ranch # 1-4
Facility ID: 447123



Photo #1 Separator, ECD, Meter Run & Weeds



Photo #2 Weeds grown around separator



Inspection Photos
Location Name: Two E Ranch # 1-4
Facility ID: 447123



Photo #3 Weeds grown around ECD



Photo #4 Tank Battery



Inspection Photos
Location Name: Two E Ranch # 1-4
Facility ID: 447123



Photo #5 Weeds grown around crude oil tank



Photo #6 Weeds grown around produce water tank

