

Inspection Photos
Location Name: Jack Berger A #6
Location ID: 311312



Photo #1 WH sign faded



Photo #2 PU



Inspection Photos
Location Name: Jack Berger A #6
Location ID: 311312



Photo #3 Weeds overgrown around PU



Photo #4 Weeds overgrown around Electric transformers, panel and meter box.



Inspection Photos
Location Name: Jack Berger A #6
Location ID: 311312



Photo #5 electric panel appears to be shut off



Photo #6 Stained soil around flow line riser

Inspection Photos
Location Name: Jack Berger A #6
Location ID: 311312




Photo #7 electric panel appears to be shut off