

Inspection Photos
Location Name: Jack Berger A #3
Location ID: 317740



Photo #1 WH sign



Photo #2 PU

Inspection Photos
Location Name: Jack Berger A #3
Location ID: 317740



Photo #3 fence around WH in disrepair