

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #1 WH sign

Photo #2 Stained soil around WH

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #3 PU

Photo #4 TB sign top left of catwalk

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #5 TB

Photo #6 Heated horiz. Sep. overgrown weeds

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #7 no guard over electric motor pulley belt

Photo #8 no guard over PU belts

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #9 unused equipment stored on location

Photo #10 unused equipment stored on location

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #11 unused equipment stored on location PUs

Photo #12 unused equipment stored on location tubing

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #13 unused equipment stored on location ECDs

Photo #14 unused equipment stored on location tubing

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #15 unused equipment stored on location sucker rod

Photo #16 unused equipment stored on location riser pipe, cement lids

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #17 unused equipment stored on location valves

Photo #18 Stained soil inside heated horis.sep housing

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #19 possible leak in heated horz. Sep. plumbing

Photo #20 Misc. unused equipment stored on location

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #21 Misc. unused equipment stored on location

Photo #22 Misc. unused equipment stored on location

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #23 Misc. unused equipment stored on location

Photo #24 Misc. unused equipment stored on location

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #25 Gas meter run

Photo #26 Misc. unused equipment stored on location

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #27 unused equipment stored on location

Photo #28 Misc. unused equipment stored on location

Inspection Photos
Location Name: Counter #2
Location ID: 317954



Photo #29 unused equipment stored on location

Photo #30 WH leaking under electrical tape