

Inspection Photos  
Location Name: SRC Williams Pad  
Location ID: 445473



Colorado Oil & Gas Conservation Commission  
40.34145, -104.89898, 1407.0m, 353°  
09/18/2019 01:44:09 PM

Lease road entrance



Colorado Oil & Gas Conservation Commission  
40.34413, -104.89776, 1448.0m, 2°  
09/18/2019 01:46:26 PM

Production facility



**Inspection Photos**  
**Location Name: SRC Williams Pad**  
**Location ID: 445473**



**Wellheads**



**Concrete vaults on north side of location**



**Inspection Photos**  
**Location Name: SRC Williams Pad**  
**Location ID: 445473**



**Concrete vault at compressor**



**Fiberglass vault**



**Inspection Photos**  
**Location Name: SRC Williams Pad**  
**Location ID: 445473**



**Trash**



**Chemical placard**



**Inspection Photos**  
**Location Name: SRC Williams Pad**  
**Location ID: 445473**



**Open electric trench**



**Unused equipment**