

# Final Reclamation Inspection

September 17, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-27370

Inspection Document #: 697500593

Weld County, CO

NENW Section 32 T7N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: ROTHARMEL #21-32  
API: 05-123-27370



**Photo 1.** Photo taken from the well location, facing South. Photo illustrates the area around the well location has been recently mowed. There was a high establishment of weeds around the wellhead area.



**Photo 2.** Photo taken from the well location, facing North. Photo illustrates some areas have already been mowed.



Inspection Photos  
Location Name: ROTHARMEL #21-32  
API: 05-123-27370



**Photo 3.** Photo taken from the battery location, facing South. Photo illustrates the Operator has failed to complete final reclamation activities. Note: Surface owner was at the tank battery location and indicated the desire to leave the gravel in-place for hay and equipment storage.



Inspection Photos  
Location Name: ROTHARMEL #21-32  
API: 05-123-27370



**Photo 4.** Photo taken from the battery location, facing East. See comments under Photo 3.

Inspection Photos  
Location Name: ROTHARMEL #21-32  
API: 05-123-27370



**Photo 5.** Photo taken from the battery location, facing North. See comments under Photo 3.