

Final Reclamation Inspection

September 17, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-27373

Inspection Document #: 697500595

Weld County, CO

NWNW Section 32 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ROTHARMEL #11-32
API: 05-123-27373



Photo 1. Photo taken from the well location, facing South. Photo illustrates the area around the well location has been recently mowed. There was a high establishment of weeds around the wellhead area.

Inspection Photos
Location Name: ROTHARMEL #11-32
API: 05-123-27373



Photo 2. Photo taken from the battery location, facing South. Photo illustrates the Operator has failed to complete final reclamation activities. Note: Surface owner was at the tank battery location and indicated the desire to leave the gravel in-place for hay and equipment storage.

Inspection Photos
Location Name: ROTHARMEL #11-32
API: 05-123-27373



Photo 3. Photo taken from the battery location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: ROTHARMEL #11-32
API: 05-123-27373



Photo 4. Photo taken from the battery location, facing North. See comments under Photo 2.