

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2019

Submitted Date:

09/12/2019

Document Number:

696200764

FIELD INSPECTION FORM

Loc ID 304971	Inspector Name: Trujillo, Aaron	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																			
Operator Information: OGCC Operator Number: 66190 Name of Operator: OMIMEX PETROLEUM INC Address: 7950 JOHN T WHITE ROAD City: FORT WORTH State: TX Zip: 76120				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE																			
Contact Information: <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>michelle_lewis@omimexgroup.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment			michelle_lewis@omimexgroup.com												
Contact Name	Phone	Email	Comment																				
		michelle_lewis@omimexgroup.com																					
Inspected Facilities: <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> <tr> <td>277235</td> <td>WELL</td> <td>PA</td> <td>08/11/2012</td> <td>GW</td> <td>125-09213</td> <td>BLEDSON STATE 16-36-3-44</td> <td>RI</td> </tr> </table>								Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	277235	WELL	PA	08/11/2012	GW	125-09213	BLEDSON STATE 16-36-3-44	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																
277235	WELL	PA	08/11/2012	GW	125-09213	BLEDSON STATE 16-36-3-44	RI																
General Comment: <p>On 9/11/2019, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at Omimex Petroleum's Bledsoe State 16-36-3-44 location in Yuma County, Colorado.</p> <p>The following alleged compliance issues were observed during this inspection: 1004.a: Anchors and trash debris observed remaining on location</p> <p>Refer to the "Reclamation" section of this inspection report for additional details.</p> <p>Refer to the photo-documentation of the observed compliance issues attached to this report.</p> <p>Any corrective action(s) from previous inspections that have not been addressed are still applicable.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p>																							

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: Non cropland

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed **Fail** _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: This location does not meet 1004 final reclamation requirements.

It was observed that anchors remain on the Northwest, Southwest and Southeast ends of the location. Various trash debris was also observed.

Records show well PA 8/11/2012, anchors/debris should have been removed by 11/11/2012

Corrective Action:	Comply with 1004.a. Remove trash debris and remaining surface equipment. Conduct additional reclamation as needed to ensure location complies with 1004.a vegetative requirements.	Date	10/31/2019
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402174228	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935346
696200765	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935344