

Inspection Photos
Location Name: Milton H Nelson Unit B#1
Location ID: 336292



Photo 1 WH. Wells head sign has been replaced and weeds cut on entire location



Photo 2 PU base and electric breaker box have not been removed but still within the corrective action date.