


**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**COGIS Map view of Kannah Creek area showing access road  
with entrance off Kannah Creek Rd.**



**GoogleEarth view of Kannah Creek area.  
Image date 6/17/2016**

**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Google Earth view of Facility and access road off Kannah Creek Rd.**



**Google Earth view of Facility**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Gate at entrance of access road off Kannah Creek rd.  
Looking N.**



**Gate at entrance of access road off Kannah Creek rd. Looking N.  
Eroded and failing wattles on W side.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Waddles at entrance on W side. Looking S.**



**Weeds and erosion inside gate. Looking S.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Erosion on access road. Looking E.**



**Weeds along access road. Looking NW.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Approach to facility at gathering line crossing. Looking SW.**



**Gathering line right of way . Looking NE.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Tanks of various styles. Located outside fenced area on access road NE of facility. Looking SW.**



**Various strings of tubing, casing and sucker rods. Located outside fenced area on access road NE of facility. Looking NE.**

**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Collection of cement barricades. Located outside fenced area on access road NE of facility. Looking SW.**



**Overview of facility from outside fence . NE corner looking SW**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Gathering line riser, soil pile, cement barricades. Located outside fenced area on access road NE of facility. View from entrance gate looking NE.**



**Gathering line risers inside NE corner of facility fenced area. Looking SE.**

**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Inside entrance gate looking SE.**



**Inside entrance gate looking SW.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Inside entrance gate looking SW.**



**Inside entrance gate looking W.**

**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Google Earth close-up of facility. Top of page is NW

**Inspection Doc # 693801128**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**300 bbl tank with metal berms. Looking NE**  
**No labels.**



**300 bbl tank with metal berms. Looking NW**  
**No labels.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Separator/Dehydrator located near SE corner of facility.  
Looking SE.**



**Separator/Dehydrator located near SE corner of facility.  
Looking S.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**JT skid on SW edge of facility. Looking W.**



**JT skid on SW edge of facility. Looking NW.**

**Weeds**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**18,000 gal bullet tank on SW edge of facility. Looking W.**



**Gauge on 18,000 gal bullet tank on SW edge of facility**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**SW side of compressor building looking N.  
No compressor inside**



**NE side of compressor building looking S.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Sacks of drilling chemicals.**



**Contaminated soil containment.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Storage of barrels of unknown chemicals.**



**Storage of barrels of unknown chemicals.**

**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Storage of barrels of unknown chemicals.**



**Storage of barrels of unknown chemicals.  
4" freeboard in tank. Oil on water.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Storage of totes of unknown chemicals  
inside compressor building**



**Barrels of unknown chemicals  
inside compressor building**

**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Unused well location prod Water/ Crude oil tanks**



**Unused well location separators and meter housings.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Unused well location separators**



**Scrap timbers and trash**

**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Rig equipment on matting with no containment.**



**Accumulated oil and debris on matting under draw works.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**Rolls of liner materiel. Weeds**



**Assorted wellheads and pipe.**



**FRAM OPERATING LLC – 10310**

**Facility ID # 414680**

**REEDER MESA GAS COMPRESSOR**

**Inspection Date : 9/17/2019**



**NW corner of fenced area looking SE**



**NW corner of fenced area looking SW**